

January 14th, 2025

## ADDENDUM 2- JPS RFP # 1010506 -GT10 Rotor Replacement

The purpose of this addendum is to provide feedback to queries received regarding this RFP. Note the queries as well as JPS' feedback (in blue) below:

## 1. Existing Rotor Information

Please provide the operational history of the rotor that is being replaced. Specifically:

a. Factored Fired Hours.

Answer – 100,403.92 hours

b. Factored Fired Starts.

Answer– 9,524.00 Starts

## 2. Additional Questions - Rotor Replacement

a. Please provide the reasons for JPSCo to replace the rotor, considering that this unit is a peaker and operates very low hours.

Answer- The starts have exceeded the OEM recommendation of 5000 factored starts.

b. Are there any additional upgrades being considered by JPSCo for GT10.

Answer– No additional upgrades are being considered.

c. Please provide the expected fired hours/fired starts per year for GT10 after the rotor is replaced.

Answer– An average of 420 factored starts per year.

d. If JPSCo is considering a refurbished rotor option, please confirm if JPSCo has a range of remaining fired hours/fired starts being considered for the refurbished rotor (i.e., 50,000 hours, 100,000 hours)

Answer- JPS is seeking to procure a rotor that has a maximum of 2000 starts.

**3.** We are hereby requesting an extension to the deadline for submission of bid to January, 31<sup>st</sup> 2025. Kindly advise if this can be accommodated.

Answer- After careful consideration a decision has been taken to grant the requested extension.

The revised deadline for submission of proposals in response to this RFP is as follows:

• 11:59pm (Jamaica Local Time) on Friday January 31, 2025.

[END OF DOCUMENT]